inspectcars

KNOW BEFORE YOU BUY

Vehicle Inspection Report

Report ID: **IC-SAMPLE**
Inspected: **29 Nov 2026, 08:12 am IST**
Inspector: **Sample Inspector (illustrative)**
Generated: **29 Nov 2026**

Maruti Suzuki Swift VXi 2019

Premium Inspection - illustrative sample · MP09XX1234

VEHICLE DETAILS

Make / Model	**Maruti Suzuki Swift VXi**
Year	**2019**
Variant	**VXi**
Fuel	**petrol**
Odometer	**48,230 km**
Fuel Level	**half**

INSPECTION DETAILS

Customer	**Sample Customer**
Mobile	**+91 90000 00000**
Inspected on	**29 Nov 2026, 08:12 am IST**
Booked for	29 Nov 2026
Location	**Indore, Madhya Pradesh**
Pincode	**452001**

OVERALL VERDICT

7 / 10

Buy with Repairs

ILLUSTRATIVE SAMPLE - not an inspection of a real vehicle. This example shows a front-left tyre finding that needs attention. Other results demonstrate the report layout. Actual reports contain the observations and photos recorded during your inspection.

Vehicle Identity & Documents

ITEM	RATING	REMARKS
Registration number matches the RC	Good	Illustrative result only.
Visible VIN/chassis number matches the RC	Good	Illustrative result only.
Accessible engine number matches the RC	Good	Illustrative result only.
Make and model match the RC	Good	Illustrative result only.
Fuel type matches the RC	Good	Illustrative result only.
Registered owner details on presented RC	Good	Illustrative result only.
Insurance document validity	Good	Illustrative result only.
PUC document validity (where applicable)	Good	Illustrative result only.
Hypothecation entry on presented RC	Good	Illustrative result only.
Available service records and recorded mileage	Good	Illustrative result only.

Body Panels & Exterior

ITEM	RATING	REMARKS
Bonnet condition and alignment	Good	Illustrative result only.

ITEM	RATING	REMARKS
Roof condition	Good	Illustrative result only.
Front bumper condition and mounting	Good	Illustrative result only.
Rear bumper condition and mounting	Good	Illustrative result only.
Front-left door condition and alignment	Good	Illustrative result only.
Front-right door condition and alignment	Good	Illustrative result only.
Rear-left door condition and alignment	Good	Illustrative result only.
Rear-right door condition and alignment	Good	Illustrative result only.
Boot/tailgate condition and alignment	Good	Illustrative result only.
Visible body corrosion	Good	Illustrative result only.

Glass, Mirrors & Body Openings

ITEM	RATING	REMARKS
Front windscreen chips and cracks	Good	Illustrative result only.
Rear windscreen condition	Good	Illustrative result only.
Front-left door glass condition	Good	Illustrative result only.
Front-right door glass condition	Good	Illustrative result only.
Rear-left door glass condition	Good	Illustrative result only.
Rear-right door glass condition	Good	Illustrative result only.
Left exterior mirror condition and adjustment	Good	Illustrative result only.
Right exterior mirror condition and adjustment	Good	Illustrative result only.
Door and boot weather seals	Good	Illustrative result only.
Door, bonnet and boot latches	Good	Illustrative result only.

Exterior Lights

ITEM	RATING	REMARKS
Left dipped headlight	Good	Illustrative result only.
Right dipped headlight	Good	Illustrative result only.
High-beam headlights	Good	Illustrative result only.
Front direction indicators	Good	Illustrative result only.
Rear direction indicators	Good	Illustrative result only.
Left brake light	Good	Illustrative result only.
Right brake light	Good	Illustrative result only.
High-mounted brake light	Good	Illustrative result only.
Reverse lights	Good	Illustrative result only.
Tail and number-plate lights	Good	Illustrative result only.

Tyres & Wheels

ITEM	RATING	REMARKS
Front-left tyre tread, sidewall and age	Poor	Uneven tread wear. Have a tyre specialist assess replacement and alignment.
Front-right tyre tread, sidewall and age	Good	Illustrative result only.
Rear-left tyre tread, sidewall and age	Good	Illustrative result only.
Rear-right tyre tread, sidewall and age	Good	Illustrative result only.
Spare tyre condition or supplied repair kit	Good	Illustrative result only.
Front-left wheel rim condition	Good	Illustrative result only.
Front-right wheel rim condition	Good	Illustrative result only.
Rear-left wheel rim condition	Good	Illustrative result only.
Rear-right wheel rim condition	Good	Illustrative result only.
Tyre size and specification consistency	Good	Illustrative result only.

Engine & Fluids

ITEM	RATING	REMARKS
Cold start (record if engine already warm)	Good	Illustrative result only.
Idle stability	Good	Illustrative result only.
Abnormal engine noise	Good	Illustrative result only.
Visible exhaust smoke	Good	Illustrative result only.
Engine oil level and visible condition	Good	Illustrative result only.
Coolant level and visible condition when safe	Good	Illustrative result only.
Brake-fluid reservoir level	Good	Illustrative result only.
Visible engine oil leaks	Good	Illustrative result only.
Visible coolant leaks	Good	Illustrative result only.
Accessible drive belts and hoses	Good	Illustrative result only.

Accessible Structure & Mechanical Components

ITEM	RATING	REMARKS
Visible engine mounts	Good	Illustrative result only.
Accessible radiator and cooling fan condition	Good	Illustrative result only.
Visible exhaust and mountings	Good	Illustrative result only.
Accessible chassis rails and repair signs	Good	Illustrative result only.
Accessible floorpan corrosion and damage	Good	Illustrative result only.
Sills and jacking points	Good	Illustrative result only.
Boot floor and spare-wheel well	Good	Illustrative result only.

ITEM	RATING	REMARKS
Visible engine-bay aprons and repair signs	Good	Illustrative result only.
Accessible fuel lines and leakage signs	Good	Illustrative result only.
Accessible driveshaft/CV boots	Good	Illustrative result only.

Brakes, Suspension & Steering

ITEM	RATING	REMARKS
Brake-pedal feel while stationary	Good	Illustrative result only.
Parking-brake operation	Good	Illustrative result only.
Visible front-left brake disc and pad condition	Good	Illustrative result only.
Visible front-right brake disc and pad condition	Good	Illustrative result only.
Accessible brake hoses and lines	Good	Illustrative result only.
Visible front-left damper leakage	Good	Illustrative result only.
Visible front-right damper leakage	Good	Illustrative result only.
Visible rear damper leakage	Good	Illustrative result only.
Steering free play while stationary	Good	Illustrative result only.
Steering-assistance operation	Good	Illustrative result only.

Interior & Seating

ITEM	RATING	REMARKS
Driver seat upholstery and adjustment	Good	Illustrative result only.
Front passenger seat and adjustment	Good	Illustrative result only.
Rear seats and folding mechanisms	Good	Illustrative result only.
Headrests and adjustment	Good	Illustrative result only.
Dashboard and trim condition	Good	Illustrative result only.
Headlining condition	Good	Illustrative result only.
Carpets and signs of water ingress	Good	Illustrative result only.
Door trims and interior handles	Good	Illustrative result only.
Boot trim and luggage area	Good	Illustrative result only.
Unusual cabin odour or dampness	Good	Illustrative result only.

Electrical & Cabin Controls

ITEM	RATING	REMARKS
12V battery terminals and visible condition	Good	Illustrative result only.
Front-left window operation	Good	Illustrative result only.
Front-right window operation	Good	Illustrative result only.

ITEM	RATING	REMARKS
Rear-left window operation	Good	Illustrative result only.
Rear-right window operation	Good	Illustrative result only.
Central locking and available keys	Good	Illustrative result only.
Infotainment display and audio	Good	Illustrative result only.
Horn operation	Good	Illustrative result only.
Wiper and washer operation	Good	Illustrative result only.
Cabin and boot lights	Good	Illustrative result only.

Comfort & Safety Equipment

ITEM	RATING	REMARKS
Air-conditioning cooling	Good	Illustrative result only.
Blower speeds and vent controls	Good	Illustrative result only.
Front/rear demisting controls	Good	Illustrative result only.
Driver seat belt and latch	Good	Illustrative result only.
Front passenger seat belt and latch	Good	Illustrative result only.
Rear seat belts and latches	Good	Illustrative result only.
Airbag/SRS warning-lamp sequence	Good	Illustrative result only.
ABS warning-lamp sequence	Good	Illustrative result only.
Rear-door child locks	Good	Illustrative result only.
Fitted parking sensors or reversing camera	Good	Illustrative result only.

Road Test - Premium / Comprehensive

ITEM	RATING	REMARKS
Gear engagement and changes	Good	Illustrative result only.
Clutch engagement (manual vehicles)	Good	Illustrative result only.
Acceleration response	Good	Illustrative result only.
Braking response under safe road conditions	Good	Illustrative result only.
Straight-line steering tracking	Good	Illustrative result only.
Steering return after a turn	Good	Illustrative result only.
Suspension noise over normal road surfaces	Good	Illustrative result only.
Unusual vibration during road test	Good	Illustrative result only.
Abnormal transmission noise	Good	Illustrative result only.
Engine temperature indication during road test	Good	Illustrative result only.

OBD Diagnostics - Premium / Comprehensive

ITEM	RATING	REMARKS
Diagnostic communication established	Good	Illustrative result only.
Engine module stored fault codes	Good	Illustrative result only.
Pending engine fault codes	Good	Illustrative result only.
Permanent engine codes (where supported)	Good	Illustrative result only.
Emissions readiness-monitor status	Good	Illustrative result only.
Available fault freeze-frame data	Good	Illustrative result only.
ABS module faults (where accessible)	Good	Illustrative result only.
Airbag/SRS module faults (where accessible)	Good	Illustrative result only.
Transmission module faults (where accessible)	Good	Illustrative result only.
Scan findings recorded in remarks or photo evidence	Good	Illustrative result only.

Paint Thickness - Comprehensive

ITEM	RATING	REMARKS
Bonnet paint-thickness reading	N/A	Not included in the booked plan.
Roof paint-thickness reading	N/A	Not included in the booked plan.
Front-left wing paint-thickness reading	N/A	Not included in the booked plan.
Front-right wing paint-thickness reading	N/A	Not included in the booked plan.
Front-left door paint-thickness reading	N/A	Not included in the booked plan.
Front-right door paint-thickness reading	N/A	Not included in the booked plan.
Rear-left door paint-thickness reading	N/A	Not included in the booked plan.
Rear-right door paint-thickness reading	N/A	Not included in the booked plan.
Left rear quarter paint-thickness reading	N/A	Not included in the booked plan.
Right rear quarter paint-thickness reading	N/A	Not included in the booked plan.

INSPECTOR SIGN-OFF

Inspector	**Sample Inspector (illustrative)**
Inspected on	**29 Nov 2026, 08:12 am IST**
Report ID	**IC-SAMPLE**

Digitally submitted by Sample Inspector (illustrative)

Inspector signature

Disclaimer: This report reflects the condition of the vehicle as observed by the InspectCars inspector at the date and time of inspection stated above. The inspection is visual and non-invasive: no parts were dismantled, and concealed, internal or intermittent defects may not be detectable. Ratings and remarks are the inspector's professional opinion and should be read together with the overall summary. This report is not a warranty, guarantee or certification of the vehicle's future condition, roadworthiness, ownership or legal status, and InspectCars accepts no liability for issues arising after the inspection. Buyers should verify documents independently before purchase.

© 2026 InspectCars · www.inspectcars.in